



Attention!
 Obstacles should be stayed at least 1 meter away from the whole machine;
 Machine should be far away from the hypocentre(origin of shocks);
 The floor flatness of less than 5 mm;
 Input voltage floating within + -5%;